PAGE: 1 PRINT DATE: 09/15/97

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL HARDWARE

NUMBER: 05-2G-21533 -X

SUBSYSTEM NAME: COMM & TRACK: S-BAND COMMUNICATIONS

REVISION: 0

01/05/88

PART DATA

PART NAME

PART NUMBER

VENDOR NAME

VENDOR NUMBER -

LRU

: PANEL A1A2

V070-730346

SRU

: SWITCH, TOGGLE

ME452-0102-7201

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

SWITCH, NSP UPLINK DATA TOGGLE SWITCH, 2 POLE, 2 POSITION, NETWORK SIGNAL PROCESSOR (NSP) UPLINK DATA.

REFERENCE DESIGNATORS: 36V73A1A2S20

QUANTITY OF LIKE ITEMS: 1

ONE (TWO POLES FOR TWO REDUNDANT CIRCUITS)

FUNCTION:

SWITCHES THE NSP TO THE KU-BAND OR S-BAND MODE FOR UPLINK, WHEN THE GOIL IS IN THE PANEL MODE. ONE SWITCH POLE EACH IS DEDICATED TO THE "KU-BAND-S-BAND" CONTROL CIRCUIT OF THE 2 NSP'S.

PRINT DATE: 09/15/97

FAILURE MODES EFFECTS ANALYSIS FMEA -- CIL FAILURE MODE

NUMBER: 05-2G-21533-02

REVISION#:

09/15/97

SUBSYSTEM NAME: COMM & TRACK: S-BAND COMMUNICATIONS

LRU: PANEL A1A2 ITEM NAME: SWITCH, TOGGLE

CRITICALITY OF THIS

FAILURE MODE: 2/2

FAILURE MODE:

SHORT TO GROUND (INPUT) WORST CASE - CONTAMINANT OR LOOSE PART MOVES AND SEQUENTIALLY SHORTS SEVERAL INPUT TERMINALS TO CASE (GROUND).

MISSION PHASE:

LO LIFT-OFF

OO ON-ORBIT

DO DE-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY:

102 COLUMBIA

103 DISCOVERY 104 ATLANTIS

105 ENDEAVOUR

CAUSE:

PIECE-PART STRUCTURAL FAILURE, CONTAMINATION, VIBRATION, MECHANICAL SHOCK, PROCESSING ANOMALY

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN

A) N/A

B) N/A

C) N/A

PASS/FAIL RATIONALE:

A)

B)

C)

- FAILURE EFFEÇTS -

(A) SUBSYSTEM:

DUE TO THE LOSS OF THE NSP SWITCH BUFFER DRIVERS (REF. FMEA 05- 6PG-21503-1), LOSS OF ALL S-BAND PM DOWNLINK IN GCIL "PANEL" MODE DUE TO LOSS OF THE "NSP ON" SIGNAL TO THE TRANSPONDERS.

PAGE: 3 PRINT DATE: 09/15/97

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE

NUMBER: 05-2G-21533-02

(B) INTERFACING SUBSYSTEM(S):

LOSS OF PANEL MODE OPERATION, AND LOSS OF ENCRYPTION PROTECTION OF COMMANDS AND DATA.

(C) MISSION:

POSSIBLE LOSS OF MISSION DUE TO MDF DECISION AFTER LOSS OF "PANEL" "NSP ON" TO TRANSPONDERS. LOSS OF ENCRYPTION PROTECTION OF COMMANDS AND DATA.

(D) CREW, VEHICLE, AND ELEMENT(S):

NO EFFECT

(E) FUNCTIONAL CRITICALITY EFFECTS:

LOSS OF "PANEL" "NSP ON" WOULD REDUCE THE MISSION TO MDF. AFTER TWO PAILURES (THIS SWITCH, AND 1 GCIL PNL/CMD SWITCH) LOSS OF BOTH NSP, A NEXT PLS WOULD BE DECLARED.

-DISPOSITION RATIONALE-

(A) DESIGN:

REFER TO APPENDIX A, ITEM #1, TOGGLE SWITCH.

(B) TEST:

REFER TO APPENDIX A, ITEM #1, TOGGLE SWITCH.

GROUND TURNAROUND TEST

ANY TURNAROUND CHECKOUT TESTING IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

(C) INSPECTION:

REFER TO APPENDIX A, ITEM #1, TOGGLE SWITCH.

(D) FAILURE HISTORY:

CURRENT DATA ON TEST FAILURES, FLIGHT FAILURES, UNEXPLAINED ANOMALIES, AND OTHER FAILURES EXPERIENCED DURING GROUND PROCESSING ACTIVITY CAN BE FOUND IN THE PRACA DATA BASE.

(E) OPERATIONAL USE:

PAGE: 4

7 .

PRINT DATE: 09/15/97

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE

NUMBER: 05-2G-21533-02

NO CREW CORRECTIVE ACTION IS AVAILABLE TO RECOVER ENCRYPTION CAPABILITY. CREW ACTION IS REQUIRED TO REGAIN S-BAND IN GCIL COMMAND MODE OR TO USE THE UHF SYSTEM FOR VOICE COMMUNICATIONS.

- APPROVALS -

EDITORIALLY APPROVED

: BNA

EDITORIALLY APPROVED TECHNICAL APPROVAL

: JSC

: VIA APPROVAL FORM

96-CIL-019 05-20